

NOTES:  
 1. ON HORIZONTAL INSTALLATIONS THE SENSOR MUST BE MOUNTED SO THE WRENCH FLATS ARE PARALLEL TO THE SURFACE OF THE PROCESS MATERIAL. THIS WILL ALLOW THE GAP TO DRAIN FREELY.

CERTIFIED	by _____			COPYRIGHT 2002
PO # _____				AMETEK DREXELBROOK
ENG _____	3	4-02-201	<i>JS 7-10</i>	SCALE NONE
USER _____	2	8-99-332	JET 9-22-99	UNLESS OTHERWISE STATED ALL DIMENSIONS IN INCHES (MM)
_____	1	5-98-256	CS 6-18-98	DR. CDW
DE # _____	ISS.	EDO/DSR NO.	APP'D	DATE
				CK. <i>JS 7-27-00</i>

**AMETEK®**  
**DREXELBROOK**

205 KEITH VALLEY RD  
 HORSHAM, PA 19044-9986


215-674-1234  
 FAX 215-674-2731

REMOTE 24 VDC  
 VeriGAP™ SWITCH  
 MOUNTING

504-1100-001-CD2

SHT. 1 OF 2  
 OF 2 3

NO. 504-1100-001-CD2  
 SHT. 1 OF 2



CERTIFIED	by					COPYRIGHT 2002
PO #						AMETEK DREXELBROOK
ENG		3	4-02-201	<i>SG</i>	7-12-02	SCALE NONE
USER		2	8-99-332	JET	9-22-99	UNLESS OTHERWISE STATED ALL DIMENSIONS IN INCHES (MM)
		1	5-98-256	CS	6-18-98	DR. CDW
DE #		ISS	EDO/DSR NO	APP'D	DATE	CK. <i>JS 9-22-02</i>

**AMETEK<sup>®</sup>**  
**DREXELBROOK**

205 KEITH VALLEY RD  
HORSHAM, PA 19044-9988

215-674-1234  
FAX 215-674-2731

REMOTE 24 VDC  
VeriGAP™ SWITCH  
MOUNTING

504-1100-001-CD2

SHT. 2	ISS.
OF 2	3

NO. 504-1100-001-CD2

SHT. 2 OF 2