

NOTES:

1. ON HORIZONTAL INSTALLATIONS THE SENSOR MUST BE MOUNTED SO THE WRENCH FLATS ARE PARALLEL TO THE SURFACE OF THE PROCESS MATERIAL. THIS WILL ALLOW THE GAP TO DRAIN FREELY.

CERTIFIED	by _____				COPYRIGHT 2002
PO #	4	4-02-201	Jet	7-12-02	AMETEK DREXELBROOK
ENG	3	8-99-332	JET	9-22-99	SCALE NONE
USER	2	1-96-341	GLM	2-19-96	UNLESS OTHERWISE STATED ALL DIMENSIONS IN INCHES (MM)
	1	8-94-344	GLM	9-13-94	DR. CDW
DE #	ISS.	EDO/DSR NO.	APP'D	DATE	CK. <i>JB 7-12-02</i>

**AMETEK**®  
**DREXELBROOK**

205 KEITH VALLEY RD  
HORSHAM, PA 19044-9988

215-674-1234  
FAX 215-674-2731


MOUNTING GAP SWITCH  
24 VDC

504-1100-001-CD1

SHT. 1 OF 2  
ISS. OF 2 4

NO. 504-1100-001-CD1

SHT. 1 OF 2



CERTIFIED	by					COPYRIGHT 2002	<h1>AMETEK®</h1> <h1>DREXELBROOK</h1>	GAP SWITCH WIRING, 24 VDC	
PO #		4	4-02-201	<i>SCF</i>	<i>1-12-01</i>	AMETEK DREXELBROOK			
ENG		3	8-99-332	JET	9-22-99	SCALE NONE			
USER		2	1-96-341	GLM	2-19-96	UNLESS OTHERWISE STATED ALL DIMENSIONS IN INCHES (MM)			
		1	8-94-344	GLM	9-13-94	DR. CDW			
DE #		ISS.	EDO/DSR NO.	APP'D	DATE	CK. <i>DS 8-27-02</i>	205 KEITH VALLEY RD HORSHAM, PA 19044-9986	215-674-1234 FAX 215-674-2731	504-1100-001-CD1
									SHT. 2 OF 2
									ISS. OF 2

NO. 504-1100-001-CD1

SHT. 2 OF 2